Electric blanket **FIRES** can be fatal!

Electric blankets cause countless fires each year, and at a recent Nottinghamshire County Council Trading Standards safety event, 68% of blankets brought into the event failed safety tests.

There are simple ways to stop a blanket causing a fire in your home. If your blanket (or its flex) shows any of these danger signs, you should have it checked or replaced:

- scorch marks
- fraying fabric
- exposed elements
- creasing or folding
- soiling
- damp patches

- tie tapes damaged or missing
- worn flex
- loose connections
- an old BEAB safety mark
 (round symbol) this means it
 is more than 10 years old.







Nottinghamshire County Council Trading Standards

Electric Blanket Safety Testing Events

Unsafe electric mattress blankets can cause fires — have you ever had yours tested?

To book a **FREE** safety test appointment phone: **0115 804 4555**

23rd October 2024 - Newark Library

24th October 2024 - Retford Fire Station

25th October 2024 - Cotgrave Futures

Any electric mattress blanket that is brought to us and fails electrical safety testing will be replaced on the day with a new electric mattress blanket. You will not receive your unsafe blanket back – it will be disposed of accordingly.

The blankets that we have available as replacements are of a standard specification and we do not have any other types in stock. Please ensure you are happy to receive this blanket in exchange for your old blanket if it is found to be unsafe.

*Please remember to bring the power cable for the blanket with you to the event